

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Conestogo

Immediate Work Required:	Loose stair guardrail Settled/heaved and uneven cast-in place concrete walkways
Significant Other Work to be Completed Over Next 15 Years:	Replacement of the sloped asphalt shingled roofs at 2 buildings Regular repairs to the horizontal vinyl siding wall systems Repairs and phased replacement of the older window systems A geotechnical assessment of the site A structural assessment of the buildings Repairs of the structural failures and displaced foundations Regular repairs and replacement to the HVAC systems Replacement of the domestic hot water tank heaters Replacement of the older main breaker panels Rehabilitating the on-site accessibility features to a satisfactory level AODA Compliance
Total Costs Over 15 Years	\$351,938