

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Carruthers

Immediate Work Required:	Installation of a concrete cover cap atop the decommissioned on-site well
Significant Other Work to be Completed Over Next 15 Years:	Replacement of the sloped asphalt shingled roof systems at 6 buildings General repairs to the exterior wall systems of the site buildings On-going selective replacement of the exterior window and door systems Replacement of the perimeter window and exterior wall joint sealants On-going repairs and replacement of the interior finishes and appliances Replacement of one domestic hot water heater Replacement of electrical panel and associated wiring at 1 building Rehabilitating the on-site accessibility features to a satisfactory level AODA Compliance
Total Costs Over 15 Years	\$134,125