

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Kienuka

Immediate Work Required:	None noted
Significant Other Work to be Completed Over Next 15 Years:	Replacement of the sloped metal roof systems at 4 buildings General repairs to exterior wall systems On-going selective replacement of exterior windows and door systems Replacement of the perimeter window and exterior wall join sealants Repairs to the step cracking and water filtration of the foundation wall at Hyatt On-going repairs and replacement of the interior finishes and appliances Replacement and repairs of the exterior wood stairs Replacement of 2 natural gas fired forced air furnaces Replacement of 3 domestic hot water heaters Replacement of selective electrical panels and associated wiring Rehabilitating the on-site accessibility features to a satisfactory level AODA Compliance
Total Costs Over 15 Years	\$247,701