

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Tewateno

Immediate Work Required:	Secure and anchor the huts on 1 site Repairs to the deteriorated wood stairs and the installation of guardrails Repairs to rectify the irregularities in height along walkway in Spirit Garden
Significant Other Work to be Completed Over Next 15 Years:	Replacement of sloped asphalt shingled roof systems Replacement and repairs to the exterior wall systems On-going selective replacement of exterior window and door systems Repairs to the heaving and cracked concrete floor slabs in teepees on-going repairs and replacement of interior finishes Repairs and replacement of the exterior wood stairs Allowances for re- grading of gravel driveways Replacement of two propane tanks Contingency allowance for replacement of selective electrical panels Replacement of the solar panel system battery Rehabilitating the on-site accessibility features to a satisfactory level AODA Compliance
Total Costs Over 15 Years	\$150,638