

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Woolsey

| | |
|---|---|
| Immediate Work Required: | Replacement of missing smoke detectors in Lloyd building |
| Significant Other Work to be Completed Over Next 15 Years: | Replacement of sloped asphalt shingled roof systems Miscellaneous repairs to the roof systems of 3 buildings Exterior wall, window and door repairs Ongoing replacement of the original single glazed windows throughout Replacement of concrete block foundation at 1 building Minor repairs to the structural elements of various buildings Replacement of the interior finishes within 1 building following completion of mould survey Regular repairs of the interior finishes Repairs to and modifications of various railing systems Inspections and repairs of on-site septic systems Replacement of the domestic hot water heater Rehabilitating the on-site accessibility features to a satisfactory level AODA Compliance |
| Total Costs Over 15 Years | \$430,189 |