

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Ademac

Immediate Work Required:	None noted
Significant Other Work to be Completed Over Next 15 Years:	Replacement of the sloped asphalt shingled roofs at 6 buildings Repairs to the exterior wall systems Replacement of the deteriorated and de-bonded exterior sealants Regular repairs of the interior finishes Repairs of the exterior walkways and wood stairs throughout Regular repairs and inspections on the on-site septic systems Replacement of 2 electric and 1 propane fired furnaces Replacement of 4 domestic hot water heaters Replacement of the fire alarm panel in Trillium Lodge AODA Compliance
Total Costs Over 15 Years	\$378,888