

CAMP PROPERTY DATA

CONSOLIDATED BPCA: Adelaide

Immediate Work Required:	Hilltop Storage jacking and levelling Steps with no guard rail- Edelweiss Hole in interlocking paver ramp- Adelaide House
Significant Other Work to be Completed Over Next 15 Years:	Replacement of the sloped asphalt shingled roofs 5 buildings Replacement of the sloped metal roofs atop Ranger House Garage Exterior wall, window and door repairs throughout Replacement of the original windows of 11 buildings Regular repairs to interior finishes Repairs of exterior walkways and wood stairs Replacement of the heating boilers in 2 buildings Replacement of one suspended unit heater Regular inspections and repairs of the on-site septic system Replacement of the domestic hot water heaters Replacement of the main electrical disconnect switches in 3 buildings AODA Compliance
Total Costs Over 15 Years	\$444,651